


12.10.2017 / NM

RECOMMENDATION*Opel*

| | | | |
|-------------------------|------------|---|------|
| | | Masterlift 2.30 Sav 230 Body repair | Opel |
| Item | Pcs | Designation | |
| 20849 10271 12033 | 1 | Twin-ram inground lift „body repair“ AUTOPSTENHOJ Masterlift 2.30 Sav 230 Body repair  | |
| 12276 | 1 | Recommended accessories: Cassette (230) depth 2415 mm | |
| 11099 | 1 | Pre-fitting of the hydraulic unit in the factory | |

Prices for delivery and fitting on request!

Other options: on request

No liability accepted for specifications which are subject to alteration.

AUTOPSTENHOJ
 autop Maschinenbau GmbH
 Sandkampstr. 90
 D - 48432 Rheine
 Tel.: +49 5971 860 202

AUTOPSTENHOJ
 Stenhoj A/S
 Barrit Langgade 188 - 190
 DK – 7150 Barrit
 Tel.: +45 7682 1330

www.autopstenhoj.com